



ORIGINAL

DART AEROSPACE LTD	Work Order:	
Description: Bushing	Part Number:	B67-43001-225
Inspection Dwg: B67-43001 Pg18	Rev: B1	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Measured by:		Audited by:		Prototype Approval:	N/A
Date:	06/11/25	Date:	08/11/25	Date:	N/A

Rev	Date	Change	Revised by	Approved
A	08.07.25	New Issue	KJ/DD	

Date: Monday, 24/11/2008 8:42:32 AM
User: Melanie Fauteux

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BUSHING

Job Number: 43711

Part Number: PB6743001225

Job Number:



Seq. #: Machine Or Operation:

Description :

6.0 QC21

FINAL INSPECTION/W/O RELEASE



08/11/26 JJ

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 08-11-25

Date: Monday, 24/11/2008 8:42:31 AM
 User: Melanie Fauteux

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services		Drawing Name	: BUSHING		
Job Number	: 43711		Part Number	: PB6743001225		
Estimate Number	: 13454		Drawing Number	: B6743001 P.18		
P.O. Number	:		Project Number	: N/A		
This Issue	: 24/11/2008	S.O. No. :	Drawing Revision	: B1		
Prsht Rev.	: NC		Material	:		
First Issue	: / /	Type : SMALL /MED FAB	Due Date	: 26/11/2008	Qty:	40 Um: Each
Previous Run	: 40272					
Written By	:					
Checked & Approved By	: MF 08-11-24					
Comment	: Est Rev:A 08-06-26 new issue EC verified by:DD					

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :	
1.0	M6061T6R0500	6061-T6 Round Bar .500"	
		Comment: Qty.: 0.1050 f(s)/Unit Total : 4.2000 f(s) 6061T6 round bar .500" BATCH: M109390	
2.0	HARDINGE	HARDINGE CNC LATHE SMALL	
		Comment: 1-TURN AS PER FOLIO FA566 & DWG B67-43001 FOLIO REV: _____ DWG REV: B1	
		2-DEBURR AS REQUIRED	
3.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE	
		Comment: INSPECT PARTS AS THEY COME OFF MACHINE	
4.0	QC8	SECOND CHECK	
		Comment: SECOND CHECK	
5.0	PACKAGING 1	PACKAGING RESOURCE #1	
		Comment: PACKAGING RESOURCE #1 Identify and Stock Location: ST438	